




# HP 7 1800 Audio Jack Replacement

This guide will help you replace the audio jack in your HP 7 1800.

Written By: Trevor Shumate



## INTRODUCTION


You will be disassembling the HP 7 1800 and using a soldering iron to replace the audio jack.

---

### TOOLS:


- [Spudger](#) (1)
  - [Portable Soldering Iron](#) (1)
  - [Tweezers](#) (1)
-

## Step 1 — Remove the back panel



- Use a Spudger to open the back panel. Be careful not to break the tabs.


## Step 2 — Desoldering the audio jack



- Desolder the top lead for the six solder points.



## Step 3 — Removing the audio jack



- Once the solder is removed, gently pull the audio jack away from the motherboard with tweezers.

---

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2017-07-15 07:32:49 PM.